

Appendix A



Photo 1. 723 Carver Lane. Note the sag in the fascia over the garage door-the interior bearing wall has settled.



Photo 2. 632 12th Street. Cracking of basement walls and veneer separation – front of house. See Photo 3 also.



Photo 3. 632 12th Street. Movement of front basement wall has caused the stone veneer to separate from the first story wall.




Photo 4. 632 12th Street. Working crack in basement wall. The steel plate on the wall to the right is the inside anchor plate for a wall anchor (see Appendix C). Another plate is visible to the far left next to the dryer vent.



Photo 5. 632 12th Street. Crack in basement floor slab.




Photo 6. 1226 Darlene Street. Crack in corner of basement walls; this developed between September of 2005 and September of 2006.



Photo 7. 1048 Alva St. Patched crack on front wall. Note the vertical steel pier installed in front of the crack to reinforce the wall.



Photo 8. 1118 Woodland Drive. Cracked and settled driveway slab – this slab has been mudjacked and re-settled.